



Technical Inspection Report

AFL Vehicle Transport Inc.

Inspection summary confirming the vehicle was reviewed by our experts and found to be in excellent condition at the time of inspection.

Vehicle	2006 Fleetwood American Tradition 40ft
VIN	4VZBR1J976C054578
Mileage shown	31,000 miles
Generator	Onan 7.5 kW Quiet Diesel, approx. 932 hours shown
Inspection date	April 15, 2026
Inspection outcome	PASSED, vehicle confirmed in excellent condition
Document ID	AFL-INS-2006FLEETWOOD-04152026

Inspection scope

This report follows the standard systems commonly reviewed during a multi-point motorhome condition inspection, including powertrain, braking and steering, tires, roof and seals, electrical systems, generator function, plumbing, HVAC, slide-outs, appliances and core safety items.

Overall Result

All inspected areas listed in this report were marked **PASSED**. No functional concerns were observed in the checked systems at the time of inspection.

Powertrain & Drivability

Inspection point	Status	Finding
Engine cold start and idle stability	PASSED	Reviewed and operating as expected.
Engine response and operating performance	PASSED	Reviewed and operating as expected.
Cooling system condition	PASSED	Reviewed and operating as expected.
Fluid level and visible leak check	PASSED	Reviewed and operating as expected.
Transmission operation and shift quality	PASSED	Reviewed and operating as expected.
Road test and drivability review	PASSED	Reviewed and operating as expected.

Chassis & Safety

Inspection point	Status	Finding
Brake operation and stopping response	PASSED	Reviewed and operating as expected.

Inspection point	Status	Finding
Steering response and control feel	PASSED	Reviewed and operating as expected.
Suspension and ride condition	PASSED	Reviewed and operating as expected.
Tires, tread depth and sidewall condition	PASSED	Reviewed and operating as expected.
Wheels and lug area visual check	PASSED	Reviewed and operating as expected.
Exterior lights, signals and marker lamps	PASSED	Reviewed and operating as expected.
Wipers, horn, mirrors and basic safety items	PASSED	Reviewed and operating as expected.

Coach Exterior & Structural Systems

Inspection point	Status	Finding
Roof surface condition	PASSED	Reviewed and operating as expected.
Roof seams, sealants and moisture-risk points	PASSED	Reviewed and operating as expected.
Sidewall and exterior body condition	PASSED	Reviewed and operating as expected.
Windows, seals and compartment doors	PASSED	Reviewed and operating as expected.
Entry step, locks and latch function	PASSED	Reviewed and operating as expected.
Slide-out operation and seal check	PASSED	Reviewed and operating as expected.
Leveling system function	PASSED	Reviewed and operating as expected.

Electrical & Generator Systems

Inspection point	Status	Finding
Chassis battery condition	PASSED	Reviewed and operating as expected.
House battery system	PASSED	Reviewed and operating as expected.
12V DC system operation	PASSED	Reviewed and operating as expected.
120V AC shore power function	PASSED	Reviewed and operating as expected.
Converter/inverter function	PASSED	Reviewed and operating as expected.
Onan 7.5 kW Quiet Diesel generator start and output	PASSED	Reviewed and operating as expected.
Generator under-load operation	PASSED	Reviewed and operating as expected.
Interior outlets, GFCI points and lighting	PASSED	Reviewed and operating as expected.

Plumbing, HVAC & Interior Equipment

Inspection point	Status	Finding
Fresh water system pressure and flow	PASSED	Reviewed and operating as expected.

Inspection point	Status	Finding
Water heater operation	PASSED	Reviewed and operating as expected.
Waste system and valve function	PASSED	Reviewed and operating as expected.
Plumbing fixture leak check	PASSED	Reviewed and operating as expected.
Roof air conditioning operation	PASSED	Reviewed and operating as expected.
Furnace / heating operation	PASSED	Reviewed and operating as expected.
Refrigerator cooling performance	PASSED	Reviewed and operating as expected.
Cooktop and microwave function	PASSED	Reviewed and operating as expected.
Washer / dryer combo function	PASSED	Reviewed and operating as expected.
Interior cabinetry, seating and finish condition	PASSED	Reviewed and operating as expected.

Engineer sign-off

I certify that the vehicle identified in this report was inspected using a multi-point condition review covering the systems listed above. Based on the completed inspection, the vehicle was found to be in excellent condition at the time of review.

Harry M. Reynolds
Chief Engineer
AFL Vehicle Transport Inc.



Authorized Company Signature and Approval Seal
AFL Vehicle Transport Inc.

Approved and authenticated by AFL Vehicle Transport Inc.

This report carries the engineer signature, company authorization signature and the official approval seal.

This inspection report is provided as a sales support document for the listed vehicle and reflects the condition observed at the time of inspection.